




Instruction of sensor - single-function version

Technical details:	
Supply voltage:	12/24 DC
Transmitter:	1A (max)
Temperature range:	-20 do + 50 degrees Celsius
Turning off the sensor - press the sensor for 30sec (until button of the sensor turns off)	
Turning on the sensor - repeat steps above (press until the sensor turns on)	

Configuration	Time of pressing the sensor	Sensor signal	Handle's reaction	Examples of using
1 1 1	1sec - no longer than 3 sec	after finger recognition the sensor turns off	on the control cable (green) remains Positive potential -3sec	control with electric catch or electric lock



!!WARNING!! Installation should be done by qualified electrotechnician according to IEC 364 and EN 60204-1 or VDE !!!